Waste Site Reclassification Form

Date Submitted: 3/30/2000	Operable Unit(s): 200-SW-1	Control Number: 2000-028
Originator: B. H. Ford	Waste Site ID: 600 ESHWSA	
Phone: 372-9242	Type of Reclassification Action:	
	Rejected O	
	Closed-Out	·
	1	
This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal		
from the NPL of no action or closed-out sites will occur at a future date.		
Description of current waste site condition:		
This 90 day storage area was associated with the Exploratory Shaft Facility of the Basalt Waste Isolation Project (BWIP). All materials and waste associated with the facility have been removed and the site revegetated.		
DECEUVEIN		
77 CCC 8 0 2 0 2 CCC		
		EDMC
Basis for reclassification:	•	
WAC 173-303-630(10) requires that at closure, all dangerous waste and dangerous waste residues be removed from the containment system. However, there are no documentation requirements for this closure, and thus no referenceable records for older pads. For many of these older pads, the exact locations were not recorded and cannot be reliably re-examined at this time. By analysis of the spill response standard operating procedure and interviews with the spill response coordinator, documentation of closure of these 90 Day Storage Areas can be recreated.		
According to J. Culmer (July 31, 2000), spill response and reporting coordinator, there have been no releases to the environment from 90- Day pads. The HNF-PRO-453 Spill and Release Reporting procedure covers cleaning up releases and entering release sites, where releases		
cannot be immediately cleaned up due to the location of the release or the decision made to clean up the site at a later date, as part of the		
Operable Unit. If the release is to be cleaned up as part of the Operable Unit, then it is required that the release site and material released be added to an existing Operable Unit WIDS site or a new WIDS site created and entered into the data base. Mr. Culmer is not aware of any		
spills or releases onto 90 Day Storage Pads, that have not been cleaned up immediately, waste managed properly and then disposed of per state and federal requirements. All releases have been handled per the HNF-PRO-453 Spill and Release Reporting procedure. The releases		
state and federal requirements. All releases onto 90 Day Storage Pads that had been repe	have been handled per the HNF-PRO-453 Spill and Re orted internally to the spill response office were small I	lease Reporting procedure. The releases eaks from containers that had been
cleaned up; none of these releases migrated	off the pads and into the soil column or environment)	Thus, all evidence indicates this 90 Day
7 115-	le 141	1 0/4/2
Beyon L. Bus	- South San	0/16/2
DOE Project Manager	Signature /	Data '
Warry Son	· Winn	new 9-6-00
Ecology Project Manager	Signature	Date
	-	
		Det:
EPA Project Manager	Signature	Date